



The Flood in the Unit 2 Reactor Building of the Lungmen NPP during Typhoon SINLAKU




Ming-Te HSU
Deputy Director
Department of Nuclear Regulation
Atomic Energy Council, Taiwan

7th USNRC-TAEC Bilateral Technical Meeting
Washington D.C. May 11-13, 2009




OUTLINES

- **Sequence of Events**
- **The Affected Equipment**
- **Short-term Activities**
 - **Recovery Plan**
 - **Regulatory Activities**
- **Long-term Activities**
- **Conclusions**



Sequence of Events


- On Sep. 13th & 14th 2008, Typhoon SINLAKU hit the northern Taiwan with strong wind and heavy rains. It caused the flood in the Unit 2 Reactor Building Radwaste Tunnel of the Lungmen NPP, which is still under construction.
- Some of the pumps failed to function due to offsite power outage in the evening of 13th. The flood level thus got higher and higher. (outside of RB)
- The flood overflowed the sand bags and through the poorly sealed pipe (6 inches) towards the RB.



Sequence of Events (Cont.)


- The water flew through the hole into the RB, and flooded the pumps (not submersible pump) equipped at the basement (EL. -8200) . These 8 sets of non-submersible pump failed to function.
- The flood level eventually reached about 2 meters. (inside of RB)





Sequence of Events (Cont.)


- Morning of the 14th, flood of unit 2 of Reactor Building of the 4th NPP was identified
- Morning of the 15th, the TPC reported the flood to AEC on-duty center
- Immediately action (TPC)
 - Block the leak source
 - Got all available pumps to pump water out
 - On 16th, most of water was pumped out of the basement
 - Checked the flooded equipment thoroughly, and issued the NCR (Non Conformance Report)



The Affected Equipment

- The affected equipment :
 - CRD Pumps
 - HPCF Pumps
 - RCIC Pump, keep fill pump, drain pump
 - RHR Pumps, keep fill pumps
 - RHR HXs
 - RWCU backwash pump
 - RWCU pumps
 - RWCU HXs
 - AHUs
 - HCU
 - Quenchers
 - others
- Total: 34 sets of water pump, 12 sets of motor, 7 sets of AHU, 103 sets of HCU, etc.






Recovery Plan

■ Repair

- MOV, AOV : repaired by LCO and supported by 3th NPP, Lungmen NPP
- Motor : disassemble at outside factory
- Pump : repair in the field

■ Quality and Safety :


- Refer to EPRI “ Guidelines for the Repair of NPP Safety-Related Motors”
- Refer to INPO documents
- Refer to the domestic and international experiences
- Ask manufacturers to repair RCIC Pump, CRD Pumps



Recovery Plan (Cont.)


■ Preventive Actions

- Recheck the opening of all the buildings
- Setup the mechanism to account for all the openings
- Before typhoon, make sure all the openings are tightly sealed
- Deploy diesel submersible pump to avoid pump failure due to flood



Regulatory Activities

- **On Sep. 15, 2008, Received the event notification from TPC**
 - Asked resident inspector to observe the recovery activities
 - Release the news in the public website
- **On Sep. 16 & 17, 2008, Resident Inspector reentered the site to inspect the affected equipment**
- **On Sep. 24, 2008, TPC officially reported the event to AEC, AEC requested TPC to:**
 - Review the effectiveness and the efficiency of typhoon contingency plan and response team to ensure the history will not repeat itself
 - Refer to the domestic and international experiences to setup the recovery plan including the acceptance criteria
 - Define the examination and maintenance procedures to ensure the environmental-sensitive equipment above the flood level can perform its intended safety function
 - Setup the special procedure to ensure the affected equipment will be compliant to the operability and reliability requirements



Regulatory Activities (Cont.)


■ Notification of Violation

- Regulations on Immediate Notification Requirements and Reportable Event Report for Nuclear Reactor Facilities

- 2 hours Immediate Notification
- 1 month document report


■ Implement the preliminary investigation report

- Root Cause investigation
- Outline the activities of TPC and AEC
- Send the report to the State-owned Enterprise Commission to investigate the staff's responsibility₁₀




Regulatory Activities (Cont.)

- **State-owned Enterprise Commission**
 - Insufficient anti-typhoon contingency plan
 - Improper staffing of anti-typhoon team
 - Inadequate emergency reaction




Long-term Activities

- All affected equipments, except HCUs, have been repaired according to the recovery plan
- TPC established 「 Special maintenance plan before turnover 」 (including Post Construction Test phase)
- TPC set up 「 Special maintenance plan after turnover 」 (including Pre-operation test, Startup test, commercial operation phase)
- Site resident inspection (memorandum)
- Periodic inspection (Notice to Improve)
- Evaluate the PCT, Pre-op, Startup test result
- Enhanced supervision for at least 2 cycles after commercial operation



Conclusions

- **Identify the root cause of the event to ensure the history will not happen again**
- **Review and oversight the recovery plan, special maintenance plan to ensure the plan will be effectively implemented**
- **Ensure the affected equipment can perform its intended safety function not only in testing phase but also in operating phase**



**Thank You
for
your attention**




Unit 2 Reactor Building



Unit 2 Control Building

“日” Type opening


Radwaste Tunnel




RB EL.-8200 Flooding Sketch Map














RB Room 149 Flooding Sketch Map












Flooding
Level:
2meters

廠房規模：
60m x 57m x 63.4m(高)
地下3層(25.7m)
地上4層(37.7m)



編號	房間名稱
110	RHR PUMP RM A
111	INSTRUMENT RACK RM. DIV. 4
112	RCIC PUMP RM A
115	CORRIDOR A
117	CRD HCU RM, QUADRANT I/IV
118	INSTRUMENT RACK RM, DIV. 1
119	QUADRANT A SUMP RM
121	RHR PUMP RM B
122	HPCF PUMP RM B
123	CORRIDOR B
124	QUADRANT B SUMP RM
125	INSTRUMENT RACK RM, DIV. 2
126	CRD HCU RM, QUADRANT II/III
129	INSTRUMENT RACK RM, DIV. 3
130	HPCF PUMP RM C
131	CORRIDOR C
132	RHR PUMP RM C
133	CRD PUMP RM
140	SPCU PUMP RM
141	RWCU NONREGENERATIVE Hx RM
142	RWCU/SPDS Instr. RM
144	RWCU BACKWASH TANK RM
146	RWCU PUMP B RM
147	RWCU PUMP A RM
148	RWCU PUMP MAINTENANCE AREA
149	BACKWASH TRANSFER PUMP RM
192	ELEVATOR #1
193	STAIR #3
194	ELEVATOR #3
195	STAIR #1

反應器廠房 B4F EL -8200

參考LM31113-1U71-M1001r6

1:300 0 2000 4000 6000 8000







Guidelines for the Repair of Nuclear Power Plant Safety-Related Motors (NCIG-12)

Prepared by
NUTECH
San Jose, California
and
Strategic Technology and Resources
Winchester, Massachusetts



UNIT:
DOC NO/LER
EVENT DATE:
NSSS/AE:

LASALLE 1 & 2 (BWR)
NO: 50-373/85045
5/31/85
GENERAL ELECTRIC/SARGENT & LUNDY

UNIT:
DOC NO/LER
EVENT DATE:
NSSS/AE:

INDIAN POINT 2 (PWR)
NO: 50-247/84011
8/13/84
WESTINGHOUSE/UNITED ENGINEERS &
CONSTRUCTORS

UNIT:
DOC NO/LER NO:
EVENT DATE:
NSSS/AE:

PEACH BOTTOM 3 (BWR)
50-278/NA
1/14/84
GENERAL ELECTRIC/BECHTEL

UNIT:
DOC NO/LER NO:
EVENT DATE:
NSSS/AE:


DOEL 1 & 2 (PWR)
BELGIUM
8/5/79
ACEC WITH WESTINGHOUSE/TRACTION-
ELECTRICITE

UNIT:
DOC NO/LER NO:
EVENT DATE:
NSSS/AE:

CRYSTAL RIVER 3 (PWR)
50-302/NA
1/26/79
BABCOCK & WILCOX/GILBERT
COMMONWEALTH

UNIT:
DOC NO/LER NO:
EVENT DATE:
NSSS/AE:

OCONEE 3 (PWR)
50-287/76018
10/9/76
BABCOCK & WILCOX/DUKE POWER
COMPANY



Fuel Building, BLAYAIS NPP, France

